



Telephone: 867-678-8090 ext. 24653

Fax: 867-777-2090

May 23, 2024

Northwind Industries Ltd.
P.O. Box 1130
Inuvik, NT X0E0T0

Attention: Fred Bailey

File Number	G19Q009
Type of Operation	QUARRY SITE - Existing
Location	Km 251 quarry


Dear Fred Bailey,

An inspection of the above noted operation was conducted on May 23, 2024 by Resource Management Officers Herbert Allen and Bradley Voudrach.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-678-8090 ext. 24653.

Sincerely,

DocuSigned by:

3DC854CF70CE468...

Herbert Allen
Resource Management Officer
Department of Environment and Climate
Change Land and Water
Beaufort Delta Region

CC:

Donald Arey, Regional Superintendent, Department of Environment and Climate Change Land and Water, Beaufort Delta Region
GLWB



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Northwind Industries Ltd.	Permit Expiry Date:	December 02, 2024
Land Use Permit No.	G19Q009	Previous Inspection:	May 09, 2024
Quarrying Permit No.	2024QP0006	Inspection Date:	May 23, 2024
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 251 quarry		
Current Stage of Operation:	On-going		
Program Modifications Approved:			

Condition of Operation “A” - Acceptable “U” - Unacceptable “N/A” - Not Applicable
“N/I” - Not Inspected

Operating Condition	Aspect Inspected				
	Km 251				
Location as Permitted	A				
Time as Permitted	U				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wastes	A				

Explanatory Remarks - Km 251:

During the inspection at Km 251 on May 23, 2024 there were no concerns observed by the inspectors.

The material that was stock piled on the pit floor quarry is getting hauled away from the quarry. All the material that is stockpiled at the South East end of the pit is being crushed and removed from the quarry as well.

At this time ECC Lands has not received the post data and quarry returns for the material that was blasted, excavated and removed from the quarry. Prior to any more drilling and blasting ECC lands need the post data before anymore quarry permits are to be issued. Also ECC lands are still awaiting the pit development plan for the future work that is going to occur in the quarry.

The rest of the site looks in good order.

Representative Signature

Inspector’s Signature

DocuSigned by:
Herbert Allen
3DC854CF70CE468...



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4





ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6

