



Telephone: 867-678-8090 ext. 24653

Fax: 867-777-2090

December 7, 2023

Department of Infrastructure
106 Veterans Way
Bag Service #1
Inuvik, NT X0E0T0

Attention: Shah Alam

File Number G23H002
Type of Operation CAMP
Location James Creek Km 14.2

Dear Shah Alam,

An inspection of the above noted operation was conducted on December 06, 2023 by Resource Management Officer Herbert Allen

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-678-8090 ext. 24653.

Sincerely,

Herbert Allen
Resource Management Officer
Environment and Climate Change
Land and Water
Beaufort Delta Region

CC:

Donald Arey, Regional Superintendent, Department of Environment and Climate Change Land and Water, Beaufort Delta Region
GLWB



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Department of Infrastructure	Permit Expiry Date:	September 11, 2028
Land Use Permit No.	G23H002	Previous Inspection:	December 06, 2023
Quarrying Permit No.		Inspection Date:	December 06, 2023
Contractor:	LJ's	Subcontractor:	
Location(s) Inspected:	James Creek maintenance camp		
Current Stage of Operation:	On-going		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected
	Camp
Location as Permitted	A
Time as Permitted	A
Equipment as Approved (Type & Size)	A
Methods & Techniques	A
Facilities	A
Erosion (Control or Prevention)	A
Chemicals	A
Wildlife and Fisheries Habitat (Protection)	A
Wastes	A
Historical / Archaeological Sites	A
Fuel Storage	A
Brush Disposal	A
Restoration of Lands	A
Permits	A
Matters not Inconsistent	A
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A

Explanatory Remarks - James Creek Km 14.2:

During the inspection at the James Creek maintenance camp on December 6, 2023 there were no concerns observed by the inspector.

The site was clean and organized and in good condition.

Representative Signature

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4

