



Department of Lands
Dehcho Region
P.O. Box 150
Fort Simpson, NT X0E 0N0

Telephone: 867-695-2626 ext. 205
Fax: 867-695-2615

September 8, 2021

Paramount Resources Ltd.
Suite 2800, 421 - 7th Avenue SW
Calgary, AB T2P 4K9

Attention: Terence Hughes

File Number	MV2014X0011
Type of Operation	MISC.
Location	Well Sites A-1, A-2, A-3, A-4, B-1, B-2, Plant Site and Airstrip

Dear Terence Hughes,

An inspection of the above noted operation was conducted on August 26, 2021 by Manager, Resource Management Danielle Rogers, and Resource Management Officer II Andrew Lirette.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-695-2626 ext. 205.

Sincerely,

Danielle Rogers
Manager, Resource Management
Department of Lands
Dehcho Region

CC: Erica Janes, Regulatory Specialist, MVLWB
Melinda Lenoir- Regional Superintendent, Department of Lands, Dehcho Region
Andrew Lirette- Resource Management Officer II, Department of Lands, Dehcho Region



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Paramount Resources Ltd.	Permit Expiry Date:	June 04, 2021
Land Use Permit No.	MV2014X0011	Previous Inspection:	July 29, 2020
Quarrying Permit No.		Inspection Date:	August 26, 2021
Contractor:		Subcontractor:	
Location(s) Inspected:	Well Sites A-1, A-2, A-3, A-4, B-1, B-2, Plant Site and Airstrip		
Current Stage of Operation:	Reclamation/Remediation		
Program Modifications Approved:	N/A		

Condition of Operation “A” - Acceptable “U” - Unacceptable “N/A” - Not Applicable “N/I” - Not Inspected

Operating Condition	Aspect Inspected				
	Well Sites	Plant Site	Airstrip		
Location as Permitted	A	A	A		
Time as Permitted	A	A	A		
Equipment as Approved (Type & Size)	A	A	A		
Methods & Techniques	A	A	A		
Facilities	A	A	A		
Erosion (Control or Prevention)	A	A	A		
Chemicals	A	A	A		
Wildlife and Fisheries Habitat (Protection)	A	A	A		
Wastes	A	A	A		
Fuel Storage	A	A	A		
Brush Disposal	A	A	A		
Restoration of Lands	A	A	A		
Permits	A	A	A		

Explanatory Remarks -

Inspectors from the Department of Lands inspected the well sites, plant site and airstrip associated with the MV2014X0011 Land Use Permit on July 14 and August 26, 2021. Aerial photographs and access to the locations were done using a helicopter.

Well Sites:

A-1

Vegetation is established with limited bare soil present throughout the site. There was a sign in place where the wellhead used to be. Inspectors have no concerns with the A-1 well site and will continue to monitor the location.

A-2

Vegetation regrowth is adequate and Inspectors noted a white flowering species throughout the site. There was a sign in place where the wellhead used to be. Inspectors have no concerns with the A-2 well site and will continue to monitor the location



ENVIRONMENTAL INSPECTION REPORT

A-3
Piping near the entrance was still on site. Vegetation regrowth is adequate. There was a sign in place where the wellhead used to be. Inspectors have no concerns with the A-3 well site and will continue to monitor the location.

A-4
Vegetation regrowth is adequate and Inspectors noted a white flowering species throughout the site. There was a sign in place where the wellhead used to be. Inspectors have no concerns with the A-4 well site and will continue to monitor the location.

B-1
Vegetation regrowth is adequate. There was a fallen down sign where the wellhead used to be. Inspectors have no concerns with the B-1 well site and will continue to monitor the location.

B-2
Vegetation regrowth is adequate. The sign was fallen over where the wellhead used to be. Inspectors have no concerns with the B-2 well site and will continue to monitor the location

Plant Site:
Most of the above ground infrastructure has been removed. The ponds on site were holding water with the surge pond having sturdy fencing with bird deterrents. Vegetation regrowth is adequate. There was bison present on site at the time of the inspection. Inspectors have no concerns with the Plant Site and will continue to monitor the location.

Airstrip:
The sea cans, totes and culverts were still on site. Vegetation is present throughout the site. Inspectors have no concerns with the airstrip and will continue to monitor the location.



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1
Aerial of A-1



Figure 2
A-1 sign





ENVIRONMENTAL INSPECTION REPORT

Figure 3
Aerial of A-2



Figure 4
A-2 sign





ENVIRONMENTAL INSPECTION REPORT

Figure 5
Aerial of A-3



Figure 6
Pipes on A-3





ENVIRONMENTAL INSPECTION REPORT

Figure 7
A-3 sign



Figure 8
Aerial of A-4





ENVIRONMENTAL INSPECTION REPORT

Figure 9
A-4 sign



Figure 10
Aerial of B-1





ENVIRONMENTAL INSPECTION REPORT

Figure 11
B-1 sign fallen



Figure 12
Aerial of B-2





ENVIRONMENTAL INSPECTION REPORT

Figure 13
B-2 sign fallen



Figure 14
Aerial of plant site





ENVIRONMENTAL INSPECTION REPORT

Figure 15
Aerial of bison on plant site



Figure 16
Aerial of airstrip





ENVIRONMENTAL INSPECTION REPORT

Figure 17
Aerial of seacans, totes and culverts

