



Department of Environment and Climate Change
Land & Water Division- Dehcho
P.O Box 150
Fort Simpson, NT X0E 0N0

Telephone: 867-695-2626 ext. 205
Fax: 867-695-2615

August 29, 2023

Paramount Resource Ltd.
Suite 2800, 4217th Avenue SW
Calgary, AB T2P 4K9

Attention: Terence Hughes

File Number	MV2021A0006
Type of Operation	OIL AND GAS DRILLING - WELLSITE
Location	I-02, F-36, N-01, O-35

Dear Terence Hughes,

An inspection of the above noted operation was conducted on August 16, 2023 by Manager, Resource Management Danielle Rogers and Lands Officer Christopher Penner.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-695-2626 ext. 205.

Sincerely,

Danielle Rogers
Manager, Resource Management
Department of Environment & Climate
Change

CC: Andrew Wheeler- Regulatory Specialist, MVLWB
Laurie Nadia- Regional Land & Water Superintendent, Department of ECC, Dehcho
Christopher Penner- Lands Officer, Department of ECC, Dehcho



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Paramount Resource Ltd.	Permit Expiry Date:	July 27, 2026
Land Use Permit No.	MV2021A0006	Previous Inspection:	August 18, 2022
Quarrying Permit No.		Inspection Date:	August 16, 2023
Contractor:		Subcontractor:	
Location(s) Inspected:	I-02, F-36, N-01, O-35		
Current Stage of Operation:	Monitoring		
Program Modifications Approved:	N/A		

Condition of Operation “A” - Acceptable “U” - Unacceptable “N/A” - Not Applicable “N/I” - Not Inspected

Operating Condition	Aspect Inspected				
	Wellsites				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	U (F-36)	28.			
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Fuel Storage	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				

Explanatory Remarks -

Inspectors from the Department of Environment and Climate Change conducted an inspection of the wellsites associated with the MV2021A0006 Land Use Permit on August 16, 2023, via helicopter.

I-02: Vegetation growth is present throughout the site. The area around the sign that was noted in the previous inspection report, had a bit more vegetation present. There was water ponding at the time of the inspection. There were no signs of erosion but it was evident that bison have been present.

F-36: Vegetation growth was present throughout the site. The erosion that was noted in the previous inspection report was less noticeable but still present at the time of the inspection. There was still a riser on site.

26(1)(f) Control or Prevention of Water, Flooding, Erosion, Slides, and Subsidence of Land



ENVIRONMENTAL INSPECTION REPORT

28. **Repair Erosion:** The Permittee shall apply appropriate mitigation at the first sign of erosion.

N-01: Vegetation is present throughout the site. There were a few bare areas with little vegetation. The wellhead was removed and a sign was in its place.

O-35: Vegetation was present throughout the site. There was a sign in place where the wellhead was.

Inspectors have no further concerns and will continue to monitor.



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1
I-02



Figure 2
I-02- note ponding water





ENVIRONMENTAL INSPECTION REPORT

Figure 3
F-36



Figure 4
F-36- note erosion channel





ENVIRONMENTAL INSPECTION REPORT

Figure 5
N-01



Figure 6
N-01





ENVIRONMENTAL INSPECTION REPORT

Figure 7
O-35



Figure 8
O-35

