

Attachment 2 Photographs

Photo 1: 9606 102nd Street. PSPC Residence

FRONT VIEW OF HOUSE



Photo 2: 9606 101st Street PSPC Residence Former Fuel Oil Tank



Photo 3: 9818 101st Residence



Photo 4: 9818 101st Residence – Historical Fuel Oil Tank Not In Service Minor Leak From Adapter



Photo 5: 9818 101st Residence – Historical fuel oil tank not in service minor leak from adapter. Soil staining is surficial and estimated to be no more than a cubic meter in volume and to be transported to KBL environmental, who accepted the original PHC impacted soil



Photo 6: Drill Rig Used for Soil Sampling and Groundwater Well Installation



