



Telephone: 867-587-7205

Fax: 867-587-2928

February 14, 2022

Enbridge Pipelines
110175 101 St. NW
Edmonton, AB T5J 2J9

Attention: Bert Filion

File Number	S20P-003
Type of Operation	PIPELINES (existing)
Location	Camp, Pipeline ROW KP 158

Dear Bert Filion,

An inspection of the above-noted operation was conducted on February 10, 2022, by Manager, Resource Management Jonathan Gillingham and Resource Management Officer II Chris Ondris.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the noted conditions and the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-587-7205 or email me at Jonathan_Gillingham@gov.nt.ca.

Sincerely,

Jonathan Gillingham
Manager, Resource Management
Department of Lands – Sahtu Region

CC: Sahtu Land and Water Board
Trevor Bremner – Regional Superintendent – Sahtu Region
Chris Ondris – Resource Management Officer II – Sahtu Region



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Enbridge Pipelines	Permit Expiry Date:	September 17, 2025
Land Use Permit No.	S20P-003	Previous Inspection:	May 07, 2021
Quarrying Permit No.	N/A	Inspection Date:	February 10, 2022
Contractor:	N/A	Subcontractor:	N/A
Location(s) Inspected:	Camp, Pipeline ROW KP 158		
Current Stage of Operation:	Remediation		
Program Modifications Approved:	None		

Condition of Operation “A” - Acceptable “U” - Unacceptable “N/A” - Not Applicable “N/I” - Not Inspected

Operating Condition	Aspect Inspected					
	Camp	KP 158				
Location as Permitted	A	A				
Time as Permitted	A	A				
Equipment as Approved (Type & Size)	A	A				
Methods & Techniques	A	A				
Facilities	A	A				
Erosion (Control or Prevention)	A	A				
Chemicals	A	A				
Wildlife and Fisheries Habitat (Protection)	A	A				
Wastes	A	A				
Historical / Archaeological Sites	A	A				
Ecological Resources	A	A				
Fuel Storage	A	A				
Brush Disposal	A	A				
Restoration of Lands	A	A				
Permits	A	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A	A				

Explanatory Remarks:

On February 10, 2022, Manager, Resource Management Jonathan Gillingham, and Resource Management Officer II Chris Ondris conducted an Inspection for Land Use Permit S20P-003. The inspection was conducted via truck along the Mackenzie Valley Winter Road.

KP 158:

During the inspection, a snowcat on the pipeline ROW at KP 158, Prepping the site for remediation work. There were no concerns at this time.

Camp:

The camp is currently set up for operations. On-site, there were a total of seven large fuel



ENVIRONMENTAL INSPECTION REPORT

tanks and a fuel storage shed, as seen in figures 11, 13, 17, 18, and 22. Currently, Inspector has no concerns regarding these tanks. In addition, there were numerous pickups and heavy machinery on-site supporting drip trays. Again, Inspector has no concerns at this time.

The campsite was very neat and tidy. Figure 19 illustrates using a wildlife-proof waste disposal container for domestic waste generated by camp operations. Inspector has no concerns at this time.

Representative Signature



Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Excavator on site



Figure 2

Trailer, mobile light tower, and two pickups





ENVIRONMENTAL INSPECTION REPORT

Figure 3
Center of the camp





Figure 4
Pipeline ROW KP 158 with Snowcat





ENVIRONMENTAL INSPECTION REPORT

Figure 5
Snowcat on ROW




Figure 6
Snowcat on ROW





ENVIRONMENTAL INSPECTION REPORT

Figure 7
Portable refueling sleigh



Figure 8
Mobile light towers and forced air heaters





ENVIRONMENTAL INSPECTION REPORT


Figure 9

Heavy equipment attachments on a rig mat



Figure 10

Transport truck with drip tray





ENVIRONMENTAL INSPECTION REPORT

Figure 11

Two bermed fuel tanks on site





ENVIRONMENTAL INSPECTION REPORT

Figure 12
Spill kit on site





ENVIRONMENTAL INSPECTION REPORT

Figure 13
Bermed diesel tank and gas tank located at the camp



Figure 14
Front end loader





ENVIRONMENTAL INSPECTION REPORT

Figure 15
Material for the project



Figure 16
Propane tanks for camp operations





ENVIRONMENTAL INSPECTION REPORT

Figure 17

Fuel tank next to the camp



Figure 18

Fuel storage shed behind the camp





ENVIRONMENTAL INSPECTION REPORT

Figure 19
Garbage disposal bin



Figure 20
A tarp over some materials with pallets





ENVIRONMENTAL INSPECTION REPORT

Figure 21
Camp with some pickups



Figure 22
Smaller fuel tanks behind the camp





ENVIRONMENTAL INSPECTION REPORT

Figure 23
View from behind the camp




Figure 24
Black and grey water storage tank

