



Telephone: 867-587-7202

Fax: 867-587-2928

April 6, 2023

Enbridge Pipelines
110175 101 St. NW
Edmonton, AB T5J 2J9

Attention: Bert Filion

File Number	S20P-003
Type of Operation	PIPELINES (existing)
Location	Camp

Dear Bert Filion,

An inspection of the above noted operation was conducted on March 21, 2023, by Resource Management Officer II Meagan Betts and Manger, Wildlife and Environment Laurel McDonald.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact the undersigned via telephone at 867-587-7202, cellphone 867-587-6999, or email meagan_betts@gov.nt.ca

Sincerely,

Meagan Betts
Resource Management Officer II
Department of Lands- Sahtu Region

CC: Sahtu Land and Water Board
Trevor Bremner- Regional Superintendent, Sahtu Region



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Enbridge Pipelines	Permit Expiry Date:	September 17, 2025
Land Use Permit No.	S20P-003	Previous Inspection:	February 22, 2023
Quarrying Permit No.	N/A	Inspection Date:	March 21, 2023
Contractor:	N/A	Subcontractor:	
Location(s) Inspected:	Camp		
Current Stage of Operation:	Remediation		
Program Modifications Approved:	None		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Camp				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type and Size)	N/A				
Methods & Techniques	N/A				
Facilities	N/A				
Erosion (Control or Prevention)	N/A				
Chemicals	N/A				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Historical/Archaeological	A				
Ecological Resources	N/A				
Fuel Storage	N/A				
Brush Disposal	A				
Restoration of Lands	N/A				
Permits	N/A				
Biological and Physical Protection	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	N/A				

Explanatory Remarks:

The Land Use Permit Inspection was conducted via truck by Officers from the Department of Lands and the Department of Environment and Natural Resources with the Government of the Northwest Territories on March 21, 2023. The Inspection was limited to the camp near kilometer point (KP) 158 along the Mackenzie Valley Winter Road.

Camp:

The Inspection occurred after all equipment and material was demobilized from the site and the final clean up had occurred. During the time of the Inspection the Inspectors noted acceptable conditions for all relevant aspects of the Land Use Permit.



ENVIRONMENTAL INSPECTION REPORT

The timeline for this work occurred within the time frame identified during the last inspection and all material and equipment was removed from the site (Figure 1-7). As evident from the images throughout the report, there was no hazardous waste or garbage left at the camp site. While the site was primarily snow covered, there were some dark patches throughout the camp. These dark areas are not indicative of spills, they are areas where the soil below the snow has been exposed (3-7). Access to this site has been blocked by berms of snow to discourage unauthorized access (Figure 8).

Future inspections will occur throughout the growing season to determine if natural regeneration of vegetation is occurring on this site. There are no current concerns with restoration efforts, however, the Inspectors are unable to determine if efforts are sufficient for achieving the restoration conditions identified in the permit due to the time of the year.

Representative Signature

Meylan Bell

Inspector's Signature

Date:	March 21, 2023	Permit #:	S20P-003	Page No:	2
-------	----------------	-----------	----------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:


Figure 1

Location previously used for fleet storage prior to camp shut down



Figure 2

General area where improperly stored material was noted in previous inspection



Date:	March 21, 2023	Permit #:	S20P-003	Page No:	3
-------	----------------	-----------	----------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Figure 3

Location of light duty vehicle parking area and camp facilities prior to shut down.



Figure 4

Area with waste bins prior to camp shut down.





ENVIRONMENTAL INSPECTION REPORT

Figure 5

Camp facility area after camp shut down.



Figure 6

Alternative angle of camp facility area after final site clean up.





ENVIRONMENTAL INSPECTION REPORT

Figure 7

Site conditions after camp shut down



Figure 8

Snow berm created at camp access point.

