



Department of Lands
Dehcho Region
P.O. Box 150

Telephone: 867-695-2626 ext. 206
Fax: 867-695-2615

August 20, 2021

Nogha Enterprises
BOX 410
Fort Simpson, NT X0E 0N0

Attention: Steven Vandell

File Number	MV2017Q0033
Type of Operation	QUARRY SITE - Existing
Location	Quarry along HWY 1 at KM 518 R

Dear Steven Vandell,

An inspection of the above noted operation was conducted on August 18th, 2021 by Resource Management Officer II Andrew Lirette.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-695-2626 ext. 206.

Sincerely,

Andrew Lirette
Resource Management Officer II
Department of Lands
Dehcho Region

CC: Tyree Mullaney - Regulatory Specialist, MVLWB
Melinda Lenoir - Regional Superintendent, Department of Lands, Dehcho Region
Danielle Rogers - Manager, Resource Management, Department of Lands, Dehcho Region



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Nogha Enterprises	Permit Expiry Date:	May 23, 2023
Land Use Permit No.	MV2017Q0033	Previous Inspection:	May 12, 2020
Quarrying Permit No.	20/0021	Inspection Date:	August 18, 2021
Contractor:		Subcontractor:	
Location(s) Inspected:	Quarry along HWY 1 at KM 518 R		
Current Stage of Operation:	Ongoing		
Program Modifications Approved:	N/A		

Condition of Operation “A” - Acceptable “U” - Unacceptable “N/A” - Not Applicable “N/I” - Not Inspected

Operating Condition	Aspect Inspected				
	KM 518				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Fuel Storage	U	32.			
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				

Explanatory Remarks -

Inspectors from the Department of Lands conducted an inspection of Land Use Permit MV2017Q0033 (Quarry Permit 2020QP0021) on August 18, 2021. The inspection consisted of the quarry along HWY 1 at KM 518 R. There was one large stockpile and two small stockpiles on site. The spill catchment buoys have been removed from the waterbody behind the large stockpile. Vegetation regrowth has been occurring along the old quarry faces.

26(1)(m) Fuel Storage

Drip Trays: 32. All equipment that may be parked for two hours or more, shall have a haz-mat/drip tray under it or be sufficiently diapered. Leaky equipment shall be repaired immediately.

There was one loader on site, and it did not have a drip tray beneath it. A minor leak was noted.

Inspectors have no further concerns and will continue to monitor.



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Loader



Figure 2

No Drip Tray beneath Loader





ENVIRONMENTAL INSPECTION REPORT

Figure 3
Minor Spill beneath Loader



Figure 4
Large Stockpile





ENVIRONMENTAL INSPECTION REPORT

Figure 5
Pond with Removed Spill Catchment Buoys



Figure 6
Vegetation Regrowth

