



Telephone: 867-678-8090 Ext. 24652
Fax: 867-777-2090

August 11, 2023

Yukon Government Department of Highways and Public Works
P.O. Box 2703
Whitehorse, YT Y1A 2C6

Attention: Darryl Froese

File Number MV2019X0027
Type of Operation MISC.
Location KM 6 Camp and Fuel Storage Area

Dear Darryl Froese,

An inspection of the above noted operation was conducted on August 09, 2023 by Resource Management Officer I Bradley Voudrach and Manager, Resource Management Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-678-8090 Ext. 24652.

Sincerely,

Bradley Voudrach
Resource Management Officer I
Department of Environment and
Climate Change
Beaufort Delta Region

CC:

Donald Arey, Regional Superintendent, Department of Environment and Climate Change,
Beaufort Delta Region

AlecSandra Macdonald, Regulatory Specialist, Gwich'in Land and Water Board



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Yukon Gov. Dept. of Highways and Public Works	Permit Expiry Date:	August 30, 2025
Land Use Permit No.	MV2019X0027	Previous Inspection:	July 18, 2023
Quarrying Permit No.		Inspection Date:	August 09, 2023
Contractor:		Subcontractor:	
Location(s) Inspected:	KM 6 Camp and Fuel Storage Area		
Current Stage of Operation:	On-going		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Mackenzie Peel crossing				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Location as Permitted	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Historical / Archaeological Sites	A				
Fuel Storage	A				
Restoration of Lands	A				
Permits	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

Explanatory Remarks -

KM 6 Camp and Fuel Storage Area:

During the inspection there were a few concerns regarding the fuel and waste fuel management. Near the south side of the camp site there were two big petroleum storage tanks, one of them with a capacity exceeding 34,000 liters that did not have the pump handles secured and did not have a secondary spill containment tray for re-fueling equipment (see figure 2). The other concern was regarding waste oil near the west edge of the camp site that did not have any secondary spill containment (see figure 3). The Inspector notified Gary from Rohl (the contractor) prior to leaving and the issues were taken care of immediately.



ENVIRONMENTAL INSPECTION REPORT

The rest of the operation was clean and organized with Rohl managing the solid waste quite well with two large bins (see figure 5) and a burner for combustibles (see figure 6).

Representative Signature

B. Vonnell

Inspector's Signature

Date:	August 09, 2023	Permit #:	MV2019X0027	Page No:	2
-------	-----------------	-----------	-------------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2



Date:	August 09, 2023	Permit #:	MV2019X0027	Page No:	3
-------	-----------------	-----------	-------------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4



Date:	August 09, 2023	Permit #:	MV2019X0027	Page No:	4
-------	-----------------	-----------	-------------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6



Date:	August 09, 2023	Permit #:	MV2019X0027	Page No:	5
-------	-----------------	-----------	-------------	----------	---