



Telephone: 867-767-9187 ex. 24187
Fax: 867-873-6230

April 9, 2024

Sixty North Gold Mining Ltd.
6120 185A St.
Surrey, BC V3S 7P9

Attention: Dave R. Webb

File Number	MV2020L2-0002
Type of Operation	CLASS B – Mining and Milling
Location	Discovery Lake, NT

Dear Dave R. Webb,

An inspection of the above noted operation was conducted on March 5th, 2024, by Water Resource Officers Meaghan MacIntyre-Newell and Nahum Lee. Enclosed is a copy of the Water Use Inspection Report; no major concerns were noted.

If you have any questions, please contact me at 867-767-9187 ex.24187.

Sincerely,

Nahum Lee
Water Resource Officer
Environment and Climate Change
North Slave Region

Cc: Scott Stewart – North Slave Regional Superintendent – ECC
Meg MacIntyre-Newell – North Slave Regional Water Resource Officer – ECC
Heather Scott – MVLWB



WATER USE INSPECTION REPORT

LICENCE #:	MV2022L2-0002	EXPIRY DATE:	October 15 th , 2027
LICENCEE:	Sixty North Gold Mining Ltd.	PREVIOUS INSPECTION:	New
COMPANY REP:	Dave R. Webb	INSPECTION DATE:	March 5 th , 2024

WATER SUPPLY

Source:	Discovery Lake	Quantity Used:	Unknown
Owner/Operator:	Sixty North Gold Mining Ltd.	Meter Reading:	N/A

Indicate: A - Acceptable U - Unacceptable N/A - Not Applicable N/I - Not Inspected

Intake Facilities	N/A	Storage Structures	N/A	Treatment Systems	N/A	Recycling	N/A
Flow Meas. Device	N/A	Conveyance Lines	N/A	Pumping Stations	N/A	Chem. Storage	N/A
						Modifications	N/A

Water Supply Comments:

No operations were underway at the time of inspection.

GENERAL CONDITIONS/REPORTS/PLANS

Indicate: A - Acceptable U - Unacceptable N/A - Not Applicable N/I - Not Inspected

C &R Plan	A	Records & Reporting	A	Final Report	N/A
Geotechnical Inspection	N/A	Posting, Signage	A	Contingency Plan	A
Restorations Activities	A	Spills	A	O&M Plan	A
Maintenance	A	Modifications	N/A	Annual Report	N/A

General Condition Comments:

No concerns under the Water Licence regulated activities were noted as the site was inactive at the time of inspection. Significant fire damage was noted during the inspection.

The annual licence report is overdue and must be submitted immediately. If the report cannot be submitted immediately, please contact the board to request an extension.

NON-COMPLIANCE/VIOLATIONS OF ACT OR LICENCE

No non-compliances or violations were identified during the Inspection. A follow-up inspection will be conducted during snow free conditions.

Inspector's Signature:



WATER USE INSPECTION REPORT

INSPECTION IMAGES

Figure 1 – Remains of burned camp structure.



Figure 2 – Remains of burned equipment.





WATER USE INSPECTION REPORT

Figure 3 – Bulk fuel storage containers on site.



Figure 4 – Equipment on site.

