



Telephone: 867-587-7205
Fax: 867-587-2928

August 9, 2022

Enbridge Pipelines
110175 101 St. NW
Edmonton, AB
T5J 2J9

Attention: Bert Filion

File Number	S20P-003
Type of Operation	PIPELINES (existing)
Location	Camp and

Dear Bert Filion,

The above-noted operation was inspected on June 27, 2022, by Manager, Resource Management Jonathan Gillingham.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the noted conditions and the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-587-7205 or by email at Jonathan_Gillingham@gov.nt.ca.

Sincerely,

Jonathan Gillingham
Manager, Resource Management
Department of Lands – Sahtu Region

CC: Sahtu Land and Water Board
Trevor Bremner – Regional Superintendent – Sahtu Region



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Enbridge Pipelines	Permit Expiry Date:	September 17, 2025
Land Use Permit No.	S20P-003	Previous Inspection:	February 10, 2022
Quarrying Permit No.	N/A	Inspection Date:	June 27, 2022
Contractor:	N/A	Subcontractor:	N/A
Location(s) Inspected:	Camp and		
Current Stage of Operation:	Remediation		
Program Modifications Approved:	None		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Camp	Drill Sites			
Location as Permitted	A	A			
Time as Permitted	A	A			
Equipment as Approved (Type & Size)	A	A			
Methods & Techniques	A	A			
Facilities	N/A	N/A			
Erosion (Control or Prevention)	A	A			
Chemicals	N/A	N/A			
Wildlife and Fisheries Habitat (Protection)	A	A			
Wastes	N/A	N/A			
Historical / Archaeological Sites	A	A			
Ecological Resources	A	A			
Fuel Storage	N/A	A			
Brush Disposal	A	A			
Restoration of Lands	A	A			
Permits	N/A	N/A			
Matters not Inconsistent	A	A			
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A	A			

Explanatory Remarks:

An Inspection of the Land Use Permit S20P-003 was conducted via helicopter on June 27, 2022, by Manager Resource Management Jonathan Gillingham.

Drill Sites:

During the Inspection, Inspector did not find any areas of concern. In addition, the drill sites are remediating adequately with no signs of slumping or erosion. Enbridge created a diversion dam to mitigate water from entering the excavated area, thus mitigating erosion from water runoff. Inspector believes the site will revegetate well over time. Therefore, Inspector has no concerns at this time.



ENVIRONMENTAL INSPECTION REPORT

Camp:

The Camp pad is in good condition. The area has been kept clean of waste and debris. There is a lack of vegetation currently; however, Inspector believes this site will revegetate well over time. Therefore, there are no current concerns at this time.

Representative Signature



Inspector's Signature

Date:	June 27, 2022	Permit #:	S20P-003	Page No:	2
-------	---------------	-----------	----------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Aerial of camp pad



Figure 2

Drill hole site



Date:	June 27, 2022	Permit #:	S20P-003	Page No:	3
-------	---------------	-----------	----------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Figure 3

Water diversion berm on ROW



Figure 4

Water diversion berm on ROW





ENVIRONMENTAL INSPECTION REPORT

Figure 5
Pipeline ROW

