



Telephone: 867-587-7205

Fax: 867-587-2928

March 29, 2021

Enbridge Pipelines
110175 101 St. NW
Edmonton, AB T5J 2J9

Attention: Bert Filion

File Number	S20P-003
Type of Operation	PIPELINES (existing)
Location	Camp and Drilling Sites

Dear Bert Filion,

An inspection of the above-noted operation was conducted on March 16, 2021, by Manager, Resource Management Jonathan Gillingham, and Resource Management Officer II Christopher Wasylyshyn-Ondris.

Enclosed is a copy of the Environmental Inspection Report. Please refer to all noted conditions and the comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-587-7205.

Sincerely,

Jonathan Gillingham
Manager, Resource Management
Department of Lands
Sahtu Region

CC: Sahtu Land and Water Board
Christopher Wasylyshyn-Ondris – Resource Management Officer II – Sahtu Region



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Enbridge Pipelines	Permit Expiry Date:	September 17, 2025
Land Use Permit No.	S20P-003	Previous Inspection:	February 26, 2021
Quarrying Permit No.	N/A	Inspection Date:	March 16, 2021
Contractor:	MYB Construction	Subcontractor:	N/A
Location(s) Inspected:	Camp and Drilling Sites		
Current Stage of Operation:	Active (Shutdown for the Season)		
Program Modifications Approved:	None		

Condition of Operation “A” - Acceptable “U” - Unacceptable “N/A” - Not Applicable “N/I” - Not Inspected

Operating Condition	Aspect Inspected				
	Camp	Drill Sites			
Location as Permitted	A	A			
Time as Permitted	A	A			
Equipment as Approved (Type & Size)	A	A			
Methods & Techniques	A	A			
Facilities	A	A			
Erosion (Control or Prevention)	A	A			
Chemicals	A	A			
Wildlife and Fisheries Habitat (Protection)	A	A			
Wastes	A	A			
Historical / Archaeological Sites	A	A			
Ecological Resources	A	A			
Fuel Storage	U	N/A			
Brush Disposal	A	A			
Restoration of Lands	N/A	N/A			
Permits	N/A	N/A			
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A	A			

On March 16, 2021, The Department of Lands, Sahtu Region, conducted an Inspection on Land Use Permit S20P-003. The Inspection was conducted by Manager of Resource Management Jonathan Gillingham and Resource Management Officer II, Christopher Wasylyshyn-Ondris. During the time of the Inspection, there were no significant environmental concerns.

Camp:

Inspectors were very pleased to see the condition of the camp area during the Inspection. All buildings and equipment were removed (Figures 1 – 3). There was no sign of any waste left on site.

However, Inspectors came across a small unmarked fuel cache near the fenced leased area at KP 160. There are 17 full fuel drums and 1 empty fuel drum located on the Southwest corner (Figures 4 and 5). As per **Condition 46** and **Condition 49** found in **Section 26(1)(m)**



ENVIRONMENTAL INSPECTION REPORT

Fuel Storage within the Land Use Permit, “ **The Permittee shall ensure that all fuel caches have adequate Secondary Containment.**” and “**The Permittee shall mark all Fuel Storage Container and Tanks with the Permittees Name.**”

Inspectors had moved around the drums to look for identification markings and secondary containment and could not find either. Therefore, you have received an Unacceptable condition for the Fuel Storage for this report.

Please properly mark all fuel drums with identification and ensure proper Secondary Containment as outlined in the Land Use Permit to address these issues.

If these fuel drums do not belong to Enbridge, please contact our Regional Office to discuss the Fuel Cache ownership.

Drill Sites:

During the Inspection, the Inspectors did not find any environmental concerns regarding the Drilling Sites. Inspectors plan on following up in the Summer season to assess if there are issues with all the drilling locations.

At this time, Inspectors have no concerns with the Drilling Sites.

Matters to Follow up on:

If the Fuel Cache belongs to Enbridge, properly mark all fuel drums with identification and ensure appropriate Secondary Containment as outlined in the Land Use Permit. Contact our office with an update once completed.

If these fuel drums do not belong to Enbridge, please contact our Regional Office to discuss the Fuel cache ownership.

N/A

Representative Signature

Inspector's Signature

Date:	March 16, 2021	Permit #:	S20P-003	Page No:	2
-------	----------------	-----------	----------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Camp removed, and location left clean



Figure 2

Camp removed, and location left clean





ENVIRONMENTAL INSPECTION REPORT

Figure 3

Camp removed, and location left clean





ENVIRONMENTAL INSPECTION REPORT

Figure 4
17 full and 1 empty Fuel Drums Unmarked





ENVIRONMENTAL INSPECTION REPORT

Figure 5
17 full and 1 empty Fuel Drums Unmarked





ENVIRONMENTAL INSPECTION REPORT

Figure 6
HDD Entry Point

