



Telephone: 867-678-8090

Fax: 867-777-2090

December 20, 2024

Northwind Industries Ltd.
P.O. Box 1130
Inuvik, NT X0E0T0

Attention: Fred Bailey

File Number	G19Q009
Type of Operation	QUARRY SITE - Existing
Location	KM 251

Dear Fred Bailey,

An inspection of the above noted operation was conducted on December 19, 2024 by Resource Management Officer Bradley Voudrach.

Enclosed is a copy of the Environmental Inspection Report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-678-8090 Ext. 24652.

Sincerely,

B Voudrach

Bradley Voudrach
A/ Manager, Resource Management
Department of Environment and
Climate Change
Beaufort Delta Region

CC:

Donald Arey, Regional Superintendent, Department of Environment and Climate Change,
Beaufort Delta Region

AlecSandra Macdonald, Regulatory Specialist, Gwich'in Land and Water Board



ENVIRONMENTAL INSPECTION REPORT

FOLLOW UP MATTERS FROM PREVIOUS INSPECTION OF November 29, 2024

December 3, 2024 - the Department of Environment and Climate Change requires a copy of the pre-data.

Permittee:	Northwind Industries Ltd.	Permit Expiry Date:	December 02, 2024
Land Use Permit No.	G19Q009	Previous Inspection:	November 29, 2024
Quarrying Permit No.	2024QP0006	Inspection Date:	December 19, 2024
Contractor:		Subcontractor:	
Location(s) Inspected:	KM 251		
Current Stage of Operation:	Temporarily Shutdown		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Km 251				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wastes	A				
Fuel Storage	A				

Explanatory Remarks -

Km 251:

During the inspection it was observed that the Proponent was temporarily shutdown, but there was a front-end loader in the pit loading trucks that were hauling material out of KM 251 pit.

The inspector noted changes along the east and north edge of the pit that have been previously approved by the inspector. The Proponent filled in both sections of the pit with gravel to create more floor space. Another change in the pit noted was the south end of the pit where a steep cliff previously existed was benched to create a safer working area for future projects.

The Department of Environment and Climate Change would like to remind the Proponent again to submit the pre-surveyed data.

MATTERS FOR FOLLOW UP

December 19, 2024 inspection - The Department of Environment and Climate Change are requesting a copy of all pre-surveyed data.

Representative Signature

B Voudrach

Inspector's Signature

Date:	December 19, 2024	Permit #:	G19Q009	Page No:	1
-------	-------------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Figure 1

The south wall that was benched during the project.



Figure 2

The east edge, filled in with material from the pit.





ENVIRONMENTAL INSPECTION REPORT

Figure 3

The north edge, filled in with material from the pit.

