



Telephone: 867-678-8090 ext. 24653
Fax: 867-777-2090

November 22, 2024

Government of the Northwest Territories Department of Infrastructure
Bag service # 1
106 Veteran Way
Inuvik, NT X0E0T0

Attention: Yasir Latif

| | |
|--------------------------|---|
| File Number | G21E001 |
| Type of Operation | HWY MAINTENANCE & OPERATIONS |
| Location | Km 235 |

Dear Yasir Latif,

An inspection of the above noted operation was conducted on November 20, 2024 by Resource Management Officers Herbert Allen and Bradley Voudrach.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-678-8090 ext. 24653.

Sincerely,

Herbert Allen

Herbert Allen
Resource Management Officer
Department of Environment and Climate
Change, Land and Water
Beaufort Delta Region

CC:

Donald Arey, Regional Superintendent, Department of Environment and Climate Change Land and Water, Beaufort Delta Region
GLWB



ENVIRONMENTAL INSPECTION REPORT

FOLLOW UP MATTERS FROM PREVIOUS INSPECTION OF August 23, 2024

August 23, 2024 Inspection - Obtain pre-surveyed data from 2024 operation.

| | | | |
|---------------------------------|---|----------------------|-------------------|
| Permittee: | Government of the Northwest Territories Department of Infrastructure | Permit Expiry Date: | June 27, 2026 |
| Land Use Permit No. | G21E001 | Previous Inspection: | August 23, 2024 |
| Quarrying Permit No. | | Inspection Date: | November 20, 2024 |
| Contractor: | Bobs | Subcontractor: | |
| Location(s) Inspected: | Km 235 | | |
| Current Stage of Operation: | On-going | | |
| Program Modifications Approved: | | | |

Condition of Operation “A” - Acceptable “U” - Unacceptable “N/A” - Not Applicable
“N/I” - Not Inspected

| Operating Condition | Aspect Inspected | | | | |
|---|------------------|--|--|--|--|
| | Operation | | | | |
| Time as Permitted | A | | | | |
| Equipment as Approved (Type & Size) | A | | | | |
| Methods & Techniques | A | | | | |
| Facilities | A | | | | |
| Erosion (Control or Prevention) | A | | | | |
| Chemicals | A | | | | |
| Wildlife and Fisheries Habitat (Protection) | A | | | | |
| Wastes | A | | | | |
| Fuel Storage | A | | | | |
| Restoration of Lands | A | | | | |

Explanatory Remarks - Operation :

During the inspection at Km 235 on November 20, 2024 there were no concerns observed by the inspectors.

At the time of the inspection the crew were working on the crushing and stock piling of the material. There is just one loader operating at the site loading material into the crusher.

The site is getting a bit tight for space and mobility is limited in the area. The inspectors used a drone to take pictures at the site to be safe.

The rest of the site looks in good order

N/A

Representative Signature

Herbert Allen

Inspector’s Signature

| | | | | | |
|-------|-------------------|-----------|---------|----------|---|
| Date: | November 20, 2024 | Permit #: | G21E001 | Page No: | 1 |
|-------|-------------------|-----------|---------|----------|---|



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4





ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6

