



Telephone: 867-678-8090 ext. 24653
Fax: 867-777-2090

December 6, 2024

Department of Infrastructure
106 Veterans Way
Bag Service #1
Inuvik, NT X0E0T0

Attention: Yasir Latif

File Number G23H002
Type of Operation CAMPS - < 50 Man Camp
Location James Creek Km 14.2

Dear Yasir Latif ,

An inspection of the above noted operation was conducted on December 5, 2024 by Resource Management Officer Herbert Allen

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-678-8090 ext. 24653.

Sincerely,

Herbert Allen

Herbert Allen
Resource Management Officer,
Department of Environment and Climate
Change Land and Water
Beaufort Delta Region

CC:

Donald Arey, Regional Superintendent, Department of Environment and Climate Change Land and Water, Beaufort Delta Region
GLWB



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Department of Infrastructure	Permit Expiry Date:	September 11, 2028
Land Use Permit No.	G23H002	Previous Inspection:	September 12, 2024
Quarrying Permit No.		Inspection Date:	December 5, 2024
Contractor:	LJ's	Subcontractor:	
Location(s) Inspected:	James Creek Km 14.2		
Current Stage of Operation:	On-going		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected			
	Camp			
Location as Permitted	A			
Time as Permitted	A			
Equipment as Approved (Type & Size)	A			
Facilities	A			
Chemicals	U			
Wastes	A			
Fuel Storage	A			

Explanatory Remarks - Camp:

During the inspection on December 5, 2024 at the James Creek maintenance camp there was one concerns observed by the inspector.

There was a small spill of pink fluid under the front of the tractor trailer truck that was parked at the south side of the shop. The workers at the site indicated they will have it cleaned up immediately and when I was driving past on my way back to Inuvik from the border the crew were working at the site of the spill.

The rest of the site was clean and in good order.

N/A

Representative Signature

Herbert Allen

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4

