



Telephone: 867-678-8090 ext. 24653
Fax: 867-777-2090

February 15, 2024

Department of Infrastructure
106 Veterans Way
Bag Service #1
Inuvik, NT X0E0T0

Attention: **Shah Alam**

File Number G23H002
Type of Operation CAMPS - < 50 Man Camp
Location James Creek Km 14.2

Dear Shah Alam,

An inspection of the above noted operation was conducted on February 13, 2024 by Manager, Resource Management Herbert Allen and Resource Management Officer I Bradley Voudrach.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-678-8090 ext. 24653.

Sincerely,

Herbert Allen
Resource Management Officer
Department of Environment and Climate
Change Land and Water
Beaufort Delta Region

CC:
Donald Arey, Regional Superintendent, Department of Environment and Climate Change Land and Water, Beaufort Delta Region
GLWB

ENVIRONMENTAL INSPECTION REPORT

| | | | |
|--|------------------------------|-----------------------------|--------------------|
| Permittee: | Department of Infrastructure | Permit Expiry Date: | September 11, 2028 |
| Land Use Permit No. | G23H002 | Previous Inspection: | December 06, 2023 |
| Quarrying Permit No. | | Inspection Date: | February 13, 2024 |
| Contractor: | LJ's | Subcontractor: | |
| Location(s) Inspected: | James Creek Km 14.2 | | |
| Current Stage of Operation: | On-going | | |
| Program Modifications Approved: | | | |

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

| Operating Condition | Aspect Inspected | | | | |
|---|------------------|--|--|--|--|
| | Camp | | | | |
| Location as Permitted | A | | | | |
| Time as Permitted | A | | | | |
| Equipment as Approved (Type & Size) | A | | | | |
| Methods & Techniques | A | | | | |
| Facilities | A | | | | |
| Erosion (Control or Prevention) | A | | | | |
| Chemicals | U | | | | |
| Wildlife and Fisheries Habitat (Protection) | A | | | | |
| Wastes | A | | | | |
| Historical / Archaeological Sites | A | | | | |
| Fuel Storage | A | | | | |
| Brush Disposal | A | | | | |
| Restoration of Lands | A | | | | |
| Permits | A | | | | |
| Matters not Inconsistent | A | | | | |
| Sections 8 to 12 / 14 to 16 M.V.L.U.R. | A | | | | |

Explanatory Remarks - Camp:

During the inspection on February 13, 2024 at the James Creek site there was a couple of concerns observed by the inspectors.

There was hydraulic fluid leak on the snow cat that was parked at the site and there was also hydraulic fluid on the ground in front of the bay door of the shop. The spills should be cleaned up and spill tray should be put under the leaks on the snow cat and leak should be repaired.



Representative Signature



Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:
Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4

