



Telephone: 867-678-8090 ext. 24653
Fax: 867-777-2090

September 19, 2023

GNWT Department of Infrastructure
Bag Service #1, 106 Veterans Way
Inuvik, NT X0E 0T0

Attention: **Mosiul Alam**

File Number G20H006
Type of Operation CAMPS - < 50 Man Camp
Location James Creek Km 14.2

Dear Mosiul Alam,

An inspection of the above noted operation was conducted on September 18, 2023 Resource Management Officer, Herbert Allen and Resource Management Officer Bradley Voudrach.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-678-8090 ext. 24653.

Sincerely,


Herbert Allen
Resource Management Officer
Department of Environment and Climate Change Land and Water Beaufort Delta Region

CC:
Donald Arey, Acting Regional Superintendent, Department of Environment and Climate Change Land and Water, Beaufort Delta Region
GLWB



ENVIRONMENTAL INSPECTION REPORT

Permittee:	GNWT Department of Infrastructure	Permit Expiry Date:	August 05, 2023
Land Use Permit No.	G20H006	Previous Inspection:	August 24, 2023
Quarrying Permit No.		Inspection Date:	September 18, 2023
Contractor:	L.J.'s Septic Services & Contracting Ltd.	Subcontractor:	
Location(s) Inspected:	James Creek Km 14.2		
Current Stage of Operation:	On-going		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected
	James Creek Km 14.2
Equipment as Approved (Type & Size)	A
Methods & Techniques	A
Chemicals	A
Wildlife and Fisheries Habitat (Protection)	A
Wastes	A
Fuel Storage	A
Restoration of Lands	A
Permits	A
Matters not Inconsistent	A
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A
Location as Permitted	A
Time as Permitted	A

Explanatory Remarks -

James Creek Km 14.2:

During the inspection at the James Creek maintenance camp on September 18, 2023 there were no concerns observed by the inspector.

The site was clean and organized and in good condition.

Representative Signature

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:
Figure 1



Figure 2



Date:	September 18, 2023	Permit #:	G20H006	Page No:	2
-------	--------------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4

