



Deh Cho Region
P.O. Box 150
Fort Simpson, NT. X0E 0N0

Telephone: 867-695-2626 ext.206
Fax: 867-695-2615

August 30, 2016

Apache Canada Ltd.
2800 - 421 - 7th Avenue SW
Calgary, AB T2P 4K9

Attention: Lynn Huntley

File Number	MV2014X0011
Type of Operation	MISC.
Location	Well Site A-4

Dear Lynn Huntley,

An inspection of the above noted operation was conducted on July 13, 2016 by Resource Management Officer II Kyle Christiansen and Manager, Resource Management Jarret Hardisty.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-695-2626 ext.206.

Sincerely,

Kyle Christiansen
Resource Management Officer II
Department of Lands
Deh Cho Region

CC:

Permits – MVLWB

Jarret Hardisty – Manager, Resource Management, GNWT Lands, Deh Cho Region

Laurie Nadia – Regional Superintendent, GNWT Lands, Deh Cho Region



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Apache Canada Ltd.	Permit Expiry Date:	June 04, 2019
Land Use Permit No.	MV2014X0011	Previous Inspection:	July 13, 2016
Quarrying Permit No.		Inspection Date:	July 13, 2016
Contractor:		Subcontractor:	
Location(s) Inspected:	Well Site A-4		
Current Stage of Operation:	Decommissioned		
Program Modifications Approved:	None		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Well Site A-4				
Location as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Ecological Resources	A				
Brush Disposal	A				
Restoration of Lands	A				

Explanatory Remarks -

Well Site A-4:

On July 13, 2016 inspectors from the Department of Lands inspected well site A-4 which falls under Land Use Permit MV2014X0011. The permit is held by Apache Canada Ltd. for their interests in the former Pointed Mountain Gas Field near Fort Liard.

The well head was removed earlier in the year during the winter season. Some settling of soil has occurred where the well head was removed and signage for the well was placed. Inspectors found some debris and pipes lying on the ground near the access road. Vegetation has established throughout the site with some bare soil visible.

Apache Canada Ltd. has begun their processes to decommission the Pointed Mountain Gas Field resulting in the dismantling and removal of all facilities. The Department of Lands will continue to inspect the site for any issues that may arise.

Inspectors have no concerns with the operations occurring at well site A-4.

Date:	July 13, 2016	Permit #:	MV2014X0011	Page No:	1
-------	---------------	-----------	-------------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Aerial photograph of well site A-4. Photo: July 13, 2016.



Figure 2

Photo of pipes and debris found near access road for well site A-4. Photo: July 13, 2016.





ENVIRONMENTAL INSPECTION REPORT

Date:	July 13, 2016	Permit #:	MV2014X0011	Page No:	3
-------	---------------	-----------	-------------	----------	---