



Department of Lands  
Dehcho Region  
P.O. Box 150  
Fort Simpson, NT X0E 0N0

Telephone: 867-695-2626 ext. 205  
Fax: 867-695-2615

October 22, 2019

Nogha Enterprises  
BOX 410  
Fort Simpson, NT X0E 0N0

**Attention: Steven Vandell**

<b>File Number</b>	<b>MV2017Q0033</b>
<b>Type of Operation</b>	<b>QUARRY SITE - Existing</b>
<b>Location</b>	2017QP0028- Hwy 1 Km 518

Dear Steven Vandell,

An inspection of the above noted operation was conducted on October 10, 2019 by Resource Management Officer II Danielle Rogers.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-695-2626 ext. 205.

Sincerely,

Danielle Rogers  
Resource Management Officer II  
Department of Lands  
Dehcho Region

CC: MVLWB- Permits  
David Finch- Regulatory Specialist, MVLWB  
Laurie Nadia- Regional Superintendent, Department of Lands, Dehcho Region  
Kyle Christiansen- Manager, Resource Management, Department of Lands, Dehcho Region



## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	Nogha Enterprises	<b>Permit Expiry Date:</b>	May 23, 2023
<b>Land Use Permit No.</b>	MV2017Q0033	<b>Previous Inspection:</b>	New
<b>Quarrying Permit No.</b>	17/0028	<b>Inspection Date:</b>	October 10, 2019
<b>Contractor:</b>		<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	2017QP0028- Hwy 1 Km 518		
<b>Current Stage of Operation:</b>	Ongoing		
<b>Program Modifications Approved:</b>	N/A		

**Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected**

Operating Condition	Aspect Inspected				
	<b>2017QP0028</b>				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Fuel Storage	U				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				

**Explanatory Remarks -**

**2017QP0028-HWY 1 KM 518:**

Inspectors from the Department of Lands inspected the 2017QP0028 quarry permit on October 10, 2019. There was one (1) stockpile on site with some pooling water around the stockpile and throughout the site. There was one (1) loader on site with no drip tray underneath. There was no apparent staining underneath the loader at the time of inspection.

**26(1)(m) Fuel Storage**

**32. Drip Trays:** All equipment that may be parked for two hours or more, shall have a haz-mat/drip tray under it or be sufficiently diapered. Leaky equipment shall be repaired immediately.

Inspectors require the submission of monthly quarry returns by the 10<sup>th</sup> day of every month.



## ENVIRONMENTAL INSPECTION REPORT

Inspectors noted that this quarry permit (2017QP0028) expired on September 13<sup>th</sup>, 2019

Inspection Images:

**Figure 1**

**Overview of the site with pooling water**







## ENVIRONMENTAL INSPECTION REPORT

**Figure 2**  
**Loader on site with no drip tray underneath**



**Figure 3**  
**Stockpile on site**

