



Department of Environment and Climate Change  
Dehcho Region  
P.O. Box 150  
Fort Simpson, NT X0E 0N0

Telephone: 867-695-2626 ext. 205  
Fax: 867-695-2615

May 12, 2023

Nogha Enterprises  
BOX 410  
Fort Simpson, NT X0E 0N0

**Attention: Carl Lafferty and Scott Gordon**

<b>File Number</b>	<b>MV2017Q0033</b>
<b>Type of Operation</b>	<b>QUARRY SITE - Existing</b>
<b>Location</b>	<b>HWY 1 KM 518</b>

Dear Carl Lafferty and Scott Gordon,

An inspection of the above noted operation was conducted on May 09, 2023 by Manager, Resource Management Danielle Rogers and Lands Officer Christopher Penner.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-695-2626 ext. 205.

Sincerely,

Danielle Rogers  
Manager, Resource Management  
Department of ECC  
Dehcho Region

CC: Tyree Mullaney- Regulatory Specialist, MVLWB  
Kyle Christiansen- Acting Regional Land & Water Superintendent, Department of ECC, Dehcho  
Christopher Penner- Lands Officer, Department of ECC, Dehcho Region



## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	Nogha Enterprises	<b>Permit Expiry Date:</b>	May 23, 2023
<b>Land Use Permit No.</b>	MV2017Q0033	<b>Previous Inspection:</b>	August 18, 2021
<b>Quarrying Permit No.</b>	20/0021	<b>Inspection Date:</b>	May 09, 2023
<b>Contractor:</b>		<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	HWY 1 KM 518		
<b>Current Stage of Operation:</b>	Ongoing		
<b>Program Modifications Approved:</b>	N/A		

**Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected**

Operating Condition	Aspect Inspected			
	KM 518			
Location as Permitted	A			
Time as Permitted	A			
Equipment as Approved (Type & Size)	A			
Methods & Techniques	A			
Facilities	A			
Erosion (Control or Prevention)	A			
Chemicals	A			
Wildlife and Fisheries Habitat (Protection)	A			
Wastes	A			
Fuel Storage	A			
Brush Disposal	A			
Restoration of Lands	A			
Permits	A			

**Explanatory Remarks -**

Inspectors from the Department of Environment and Climate Change conducted an inspection of Land Use Permit MV2017Q0033 on May 9, 2023.

There was one stockpile on site. No equipment or fuels were noted on site at the time of the inspection. Vegetation regrowth has been occurring along the old quarry faces.

Inspectors have no further concerns and will continue to monitor.



## ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

**Figure 1**  
**Stockpile**



**Figure 2**  
**View of water filled excavation and the rest of the quarry**

