



Telephone: (867) 695-2626 ext. 206

Fax: (867) 695-2615

May 30, 2024

Nogha Enterprises
BOX 410
Fort Simpson, NT X0E 0N0

Attention: Carl Lafferty and Scott Gordon

File Number	MV2017Q0033
Type of Operation	QUARRY SITE - Existing
Location	Quarry along HWY 1 at KM 518

Dear Carl Lafferty and Scott Gordon,

An inspection of the above noted operation was conducted on May 23, 2024 by Resource Management Officer II Chad Bullock and Lands Officer Christopher Penner.

Enclosed is a copy of the Environmental Inspection Report. Inspectors had no concerns at the time of the inspection and will continue to monitor.

If you have any questions, please contact me at (867) 695-2626 ext. 206.

Sincerely,

Chad Bullock
Resource Management Officer II
Department of Environment and
Climate Change
Deh Cho Region



ENVIRONMENTAL INSPECTION REPORT

CC: Angela Love – Regulatory Specialist, MVLWB Laurie Nadia- Regional Land and Water Superintendent, Department of ECC, Dehcho Region Danielle Rogers- Manager Resource Management, Department of ECC, Dehcho Region Christopher Penner- Lands Officer, Department of ECC, Dehcho Region

Date:	May 23, 2024	Permit #:	MV2017Q0033	Page No:	2
-------	--------------	-----------	-------------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Nogha Enterprises	Permit Expiry Date:	May 23, 2025
Land Use Permit No.	MV2017Q0033	Previous Inspection:	May 09, 2023
Quarrying Permit No.	20/0021	Inspection Date:	May 23, 2024
Contractor:		Subcontractor:	
Location(s) Inspected:	Quarry along HWY 1 at KM 518		
Current Stage of Operation:	Ongoing		
Program Modifications Approved:	N/a		

Condition of Operation “A” - Acceptable “U” - Unacceptable “N/A” - Not Applicable “N/I” - Not Inspected

Operating Condition	Aspect Inspected				
	KM 518				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Fuel Storage	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				

Explanatory Remarks -
KM 518:

Inspectors from the Department of Environment and Climate Change conducted an inspection of Land Use Permit MV2017Q0033 on May 23, 2024.

There are four stockpiles on site. No equipment or fuels were noted on site at the time of the inspection. Vegetation regrowth has been occurring along the old quarry faces.

Inspectors have no further concerns and will continue to monitor.



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1
Granular material stockpile



Figure 2
Granular material stockpile





ENVIRONMENTAL INSPECTION REPORT

Figure 3
Granular material stockpile



Figure 4
Granular material stockpile





ENVIRONMENTAL INSPECTION REPORT

Figure 5
Pond + Vegetation regrowth



Figure 6
Pond + Vegetation regrowth

