



Telephone: 867-678-8090 ext. 24653
Fax: 867-777-2090

October 21, 2022

Yukon Gov. Dept. of Highways and Public Works
P.O. Box 2703
Whitehorse, YT Y1A 2C6

Attention: Darryl Froese

File Number MV2019X0027
Type of Operation MISC.
Location Mackenzie and Peel River crossings

Dear Darryl Froese,

An inspection of the above noted operation was conducted on October 19, 2022 by Manager, Resource Management Herbert Allen and Resource Management Officer II Jozef Carnogursky.

Enclosed is a copy of the Environmental Inspection Report.


If you have any questions, please contact me at 867-678-8090 ext. 24653.

Sincerely,

Herbert Allen
Manager, Resource Management
Department of Lands
Beaufort Delta Region

CC:
Donald Arey, Regional Superintendent, Department of Lands, Beaufort Delta Region
GLWB
Tyree Mullaney– Regulatory Officer, MVLWB

Bag Service 1, Inuvik, NT X0E 0T0





ENVIRONMENTAL INSPECTION REPORT

Permittee:	Yukon Gov. Dept. of Highways and Public Works	Permit Expiry Date:	August 30, 2025
Land Use Permit No.	MV2019X0027	Previous Inspection:	October 06, 2022
Quarrying Permit No.		Inspection Date:	October 19, 2022
Contractor:		Subcontractor:	
Location(s) Inspected:	Mackenzie and Peel River crossings		
Current Stage of Operation:	on-going		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected			
	Mackenzie	Peel	crossing	
Location as Permitted	A			
Time as Permitted	A			
Equipment as Approved (Type & Size)	A			
Methods & Techniques	A			
Facilities	A			
Erosion (Control or Prevention)	A			
Chemicals	A			
Wildlife and Fisheries Habitat (Protection)	A			
Historical / Archaeological Sites	A			
Fuel Storage	A			
Restoration of Lands	U			
Permits	A			
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A			

Explanatory Remarks -

Mackenzie Peel crossing:

During the inspection at the Mackenzie River and Peel River fibre line project there was only 1 concern observed by the inspectors.

There are some wood debris from the rig mats at the site that have nails and nuts and bolts in them that should be removed from the Mackenzie River site on the south side. There was also a crew working on delivering the fibre line through the conduit across the river at the Mackenzie River site.

The rest of the sites at the Peel and Mackenzie crossings were in good order and no concerns.

Representative Signature

Inspector's Signature

Date:	October 19, 2022	Permit #:	MV2019X0027	Page No:	1
--------------	------------------	------------------	-------------	-----------------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Mackenzie south side 1



Figure 2

Mackenzie south side 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3
Mackenzie south side 3



Figure 4
Mackenzie south side 4





ENVIRONMENTAL INSPECTION REPORT

Figure 5
Mackenzie south side 5



Figure 6
Peel south side





ENVIRONMENTAL INSPECTION REPORT

Figure 7
Mackenzie north side

