



Telephone: 867-678-8090 ext. 24653
Fax: 867-777-2090

December 6, 2023

Yukon Gov. Dept. of Highways and Public Works
P.O. Box 2703
Whitehorse, YT Y1A 2C6

Attention: Darryl Froese

File Number MV2019X0027
Type of Operation MISC.
Location Km 6

Dear Darryl Froese,

An inspection of the above noted operation was conducted on December 06, 2023 by Resource Management Officer Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-678-8090 ext. 24653.

Sincerely,

Herbert Allen
Resource Management Officer
Environment and Climate Change
Land and Water
Beaufort Delta Region

CC:
Donald Arey, Regional Superintendent, Department of Environment and Climate Change Land and Water, Beaufort Delta Region
GLWB



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Yukon Gov. Dept. of Highways and Public Works	Permit Expiry Date:	August 30, 2025
Land Use Permit No.	MV2019X0027	Previous Inspection:	October 26, 2023
Quarrying Permit No.		Inspection Date:	December 06, 2023
Contractor:	Rohl Global	Subcontractor:	
Location(s) Inspected:	Km 6		
Current Stage of Operation:	On-going		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Dempster Fibre Project				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	U				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Historical / Archaeological Sites	A				
Ecological Resources	A				
Fuel Storage	A				
Restoration of Lands	A				
Permits	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

Explanatory Remarks – Km 6 Fiber line camp:

During the inspection on December 6, 2023 at the km 6 Fiber Line camp there are a couple of concerns observed by the inspector.

There is a stack of plastic boxes and some other materials that are not secured very well and will be taken away by the big storms this winter.

The rest of the site looks in good order.

Representative Signature

Inspector's Signature

Date:	December 06, 2023	Permit #:	MV2019X0027	Page No:	1
-------	-------------------	-----------	-------------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4





ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6

