



Telephone: 867-678-8090 ext. 24653
Fax: 867-777-2090

October 7, 2022

Yukon Gov. Dept. of Highways and Public Works
P.O. Box 2703
Whitehorse, YT Y1A 2C6

Attention: Darryl Froese

File Number MV2019X0027
Type of Operation MISC.
Location Mackenzie and Peel River Fibre line drilling project.

Dear Darryl Froese,

An inspection of the above noted operation was conducted on October 06, 2022 by Manager, Resource Management Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-678-8090 ext. 24653.

Sincerely,

Herbert Allen
Manager, Resource Management
Department of Lands
Beaufort Delta Region

CC:
Donald Arey, Regional Superintendent, Department of Lands, Beaufort Delta Region

GLWB



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Yukon Gov. Dept. of Highways and Public Works	Permit Expiry Date:	August 30, 2025
Land Use Permit No.	MV2019X0027	Previous Inspection:	August 23, 2022
Quarrying Permit No.		Inspection Date:	October 06, 2022
Contractor:		Subcontractor:	
Location(s) Inspected:	Mackenzie and Peel River Fibre line drilling project.		
Current Stage of Operation:	On-going		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Mackenzie Peel crossing				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Historical / Archaeological Sites	A				
Fuel Storage	A				
Restoration of Lands	A				
Permits	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

Explanatory Remarks - Mackenzie Peel crossing:

During the inspection at the Tsiigetichic site, the Mackenzie and Peel River sites for the drilling project there were no concerns observed by the inspector.

All the drilling for the river crossings are done at all the sites, there were a few rig mats left at the Mackenzie crossing and some garbage debris but there was person there from JB Bruce Enterprise cleaning up the all the sites and removing any material left behind from the project. The contractor was also going to be putting the cages and markers around the fibre line conduits at each of the sites.

Department of Lands will be conducting another inspection on all the sites before freeze up.

Representative Signature

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3




Figure 4





ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6

