



Department of Environment and Climate Change  
Land and Water Division- Dehcho  
P.O Box 150  
Fort Simpson, NT X0E 0N0

Telephone: 867-695-2626 ext. 205  
Fax: 867-695-2615

August 31, 2023

Paramount Resources Ltd  
Suite 2800, 421 7th Ave SW  
Calgary, AB T2P 4K9

**Attention: Terrence Hughes**

<b>File Number</b>	<b>MV2020A0009</b>
<b>Type of Operation</b>	<b>OIL AND GAS DRILLING - WELLSITE</b>
<b>Location</b>	<b>F25/F25A, K-29, O-80, M-25, Quarry</b>

Dear Terrence Hughes,

An inspection of the above noted operation was conducted on August 15, 2023 by Manager, Resource Management Danielle Rogers and Lands Officer Christopher Penner.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-695-2626 ext. 205.

Sincerely,

Danielle Rogers  
Manager, Resource Management  
Department of Environment & Climate  
Change

CC: Andrew Wheeler, Regulatory Specialist, MVLWB  
Laurie Nadia- Regional Land and Water Superintendent, Department of ECC, Dehcho  
Christopher Penner- Lands Officer, Department of ECC, Dehcho



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Paramount Resources Ltd	Permit Expiry Date:	November 19, 2025
Land Use Permit No.	MV2020A0009	Previous Inspection:	July 14, 2023
Quarrying Permit No.	21/0002	Inspection Date:	August 15, 2023
Contractor:		Subcontractor:	
Location(s) Inspected:	F25/F25A, K-29, O-80, M-25, Quarry		
Current Stage of Operation:	Abandonment and Reclamation		
Program Modifications Approved:	N/A		

Condition of Operation “A” - Acceptable “U” - Unacceptable “N/A” - Not Applicable “N/I” - Not Inspected

Operating Condition	Aspect Inspected				
	Sites				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Fuel Storage	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				

Explanatory Remarks -

Inspectors from the Department of Environment and Climate Change conducted an inspection of the well sites and quarry that are associated with the MV2020A0009 Land Use Permit on August 15, 2023, via helicopter.

K-29: There were personnel on site at the time of the inspection. The rig was set up, a flare stack, tanks, numerous vehicles, a loader and portable office trailers. All infrastructure appeared to be in good condition and there were still miscellaneous materials on site. No erosion was observed at the time of the inspection.

O-80: There were no personnel on site at the time of the inspection. The wellhead was still present. Infrastructure appeared to be in a good condition. There was a pile of materials and debris that should be properly disposed of.

M-25: There were no personnel on site at the time of the inspection. The wellheads were still present. Infrastructure appeared to be in a good condition. There was a pile of materials and debris that should be properly disposed of.



ENVIRONMENTAL INSPECTION REPORT

F-25/F-25A: There were no personnel on site at the time of the inspection. The wellhead was still present. Infrastructure appeared to be in a good condition. The fenced off sump was overflowing. No erosion was observed.

Quarry (2021QP0002): Woody vegetation was established throughout the quarry. Material has not yet been quarried under this quarry permit. No signs of erosion were observed.

Inspectors have no concerns and will continue to monitor.





ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1  
K-29



Figure 2  
K-29 rig set up







ENVIRONMENTAL INSPECTION REPORT

Figure 3  
O-80- note debris pile



Figure 4  
O-80







ENVIRONMENTAL INSPECTION REPORT

Figure 5  
M-25



Figure 6  
M-25- note debris pile







ENVIRONMENTAL INSPECTION REPORT

Figure 7  
F-25/F-25A



Figure 8  
F-25/F-25A- note sump overflowing







ENVIRONMENTAL INSPECTION REPORT

Figure 9  
Quarry



Figure 10  
Quarry

