



Department of Lands  
Dehcho Region  
P.O. Box 150  
Fort Simpson, NT X0E 0N0

Telephone: 867-695-2626 ext. 206  
Fax: 867-695-2615

September 2, 2022

Paramount Resources Ltd  
Suite 2800, 421 7th Ave SW  
Calgary, AB T2P 4K9

**Attention: Terrence Hughes**

<b>File Number</b>	<b>MV2020A0009</b>
<b>Type of Operation</b>	<b>OIL AND GAS DRILLING - WELLSITE</b>
<b>Location</b>	<b>F-25, F-25A, K-29, M-25, O-80, Quarry</b>

Dear Terence Hughes,

An inspection of the above noted operation was conducted on August 24<sup>th</sup>, 2022 by Resource Management Officer II Andrew Lirette and Manager, Resource Management Danielle Rogers.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-695-2626 ext. 206.

Sincerely,

Andrew Lirette  
Resource Management Officer II  
Department of Lands  
Dehcho Region

CC: Andrew Wheeler – Regulatory Specialist, MVLWB  
Kyle Christiansen - Regional Superintendent, Department of Lands, Dehcho Region  
Danielle Rogers - Manager, Resource Management, Department of Lands, Dehcho Region



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Paramount Resources Ltd	Permit Expiry Date:	November 19, 2025
Land Use Permit No.	MV2020A0009	Previous Inspection:	August 23, 2021
Quarrying Permit No.	21/0002	Inspection Date:	August 24, 2022
Contractor:		Subcontractor:	
Location(s) Inspected:	F-25, F-25A, K-29, M-25, O-80, Quarry		
Current Stage of Operation:	Abandonment and Reclamation		
Program Modifications Approved:	N/A		

Condition of Operation “A” - Acceptable “U” - Unacceptable “N/A” - Not Applicable “N/I” - Not Inspected

Operating Condition	Aspect Inspected				
	Well Sites and Quarry				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Fuel Storage	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				

Explanatory Remarks –

Inspectors from the Department of Lands conducted an inspection of Land Use Permit MV2020A0009 on August 24<sup>th</sup>, 2022 via helicopter. The inspection consisted of well sites F-25/F-25A, K-29, M-25, O-80, and the Quarry located across from the barge landing.

F-25/F-25A: All infrastructure was in good condition and the fenced off sump was almost dried up. The wellhead was still present. Vegetation is growing nicely throughout the site and there were no signs of erosion.

K-29: There was another helicopter at the site during the inspection. All infrastructure was in good condition and the wellheads, along with other miscellaneous materials, were still on site. Vegetation growth was present in some areas, but there were also a lot of bare spots. No erosion was observed.



ENVIRONMENTAL INSPECTION REPORT

M-25: Infrastructure and the sump berm were both in good condition. The wellheads were still in the ground. The site had vegetation growing on most of it, however, there were a few small bare spots. No erosion was observed.

O-80: Infrastructure was in good condition except for the missing wind sock. Vegetation growth was present in most of the area, with less occurring on the access road and turn around area. No signs of erosion were identified.

Quarry (2021QP0002): Woody vegetation growth was occurring on pit benches, and smaller vegetation was growing on pit floor. Material has not yet been quarried under this quarry permit. No signs of erosion were observed.

Inspectors have no concerns and will continue to monitor.





ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1  
F-25



Figure 2  
F-25







ENVIRONMENTAL INSPECTION REPORT

Figure 3  
F-25 Sump



Figure 4  
F-25A







ENVIRONMENTAL INSPECTION REPORT

Figure 5  
F-25A Incinerator



Figure 6  
F-25A







ENVIRONMENTAL INSPECTION REPORT

Figure 7  
F-25A



Figure 8  
F-25A







ENVIRONMENTAL INSPECTION REPORT

Figure 9  
K-29



Figure 10  
K-29







ENVIRONMENTAL INSPECTION REPORT

Figure 11  
Other Helicopter at K-29



Figure 12  
M-25







ENVIRONMENTAL INSPECTION REPORT

Figure 13  
M-25 and Sump



Figure 14  
M-25







ENVIRONMENTAL INSPECTION REPORT

Figure 15  
O-80



Figure 16  
O-80







ENVIRONMENTAL INSPECTION REPORT

Figure 17  
O-80



Figure 18  
Quarry

