



Department of Environment and Climate Change
Land and Water Division-Dehcho
P.O Box 240
Fort Simpson, NT X0E 0N0

Telephone: 867-695-1972

April 3, 2025

GNWT - INF
PO Box 1320
Yellowknife, NT X1A 2L9

Attention: Terry Brookes

File Number	MV2023E0032
Type of Operation	ROADS, all season (during const)
Location	KM 74.5 Quarry and associated camp

Dear Terry Brookes,

An inspection of the above noted operation was conducted on March 12, 2025 by Manager, Resource Management Danielle Rogers and Lands Officer Christopher Penner.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-695-1972.

Sincerely,

Danielle Rogers
Manager, Resource Management
Department of Environment & Climate
Change

CC: Tyree Mullaney- Regulatory Specialist, MVLWB
Christopher Penner- Lands Office, Department of Environment and Climate Change, Dehcho



ENVIRONMENTAL INSPECTION REPORT

Permittee:	GNWT - INF	Permit Expiry Date:	December 20, 2028
Land Use Permit No.	MV2023E0032	Previous Inspection:	December 10, 2024
Quarrying Permit No.	20/0020;21/0008;21/0020;21/0022;21/002321/0024;21/	Inspection Date:	March 12, 2025
Contractor:		Subcontractor:	
Location(s) Inspected:	KM 74.5 Quarry and associated camp		
Current Stage of Operation:	Crushing and hauling stockpile		
Program Modifications Approved:	N/A		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected			
	KM 74.5			
Location as Permitted	A			
Time as Permitted	A			
Equipment as Approved (Type & Size)	A			
Methods & Techniques	A			
Facilities	A			
Erosion (Control or Prevention)	A			
Chemicals	A			
Wildlife and Fisheries Habitat (Protection)	A			
Wastes	A			
Fuel Storage	A			
Brush Disposal	A			
Permits	A			

Explanatory Remarks -

Inspectors from the Department of Environment and Climate Change conducted an inspection of the KM 74.5 quarry and the associated camp located at KM 75 on March 12, 2025.

KM 74.5: On site there was a trailer with equipment/materials, used hydraulic oil, hydraulic oil containers in a drip tray. The drip tray should be cleared of snow to prevent any leaks or spills transferring to the ground. Crushing was actively taking place with semi's coming in to transport the material to Fort Liard. The salvageable timber was piled in an area that will be easy access to the public.

The camp had a 90,000 L diesel tank and Inspectors noted a spill kit was placed near the tank as noted in the previous inspection report. The generator trailer, 6 Atco trailers, 2 propane tanks were still on site. Inspectors noted piles of used containers but were informed that they were being transported to Fort Simpson that evening to be properly disposed of.

Inspectors will continue to monitor.



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Crushed Stockpile



Figure 2

Quarried Stockpile





ENVIRONMENTAL INSPECTION REPORT

Figure 3
Semi being loaded



Figure 4
Crusher





ENVIRONMENTAL INSPECTION REPORT

Figure 5
Trailer with supplies



Figure 6
Used oil and empty pails





ENVIRONMENTAL INSPECTION REPORT

Figure 7

Camp: Diesel tank with spill kit



Figure 8

Camp: Loader





ENVIRONMENTAL INSPECTION REPORT

Figure 9

Camp: Pile of empty pails



Figure 10

Camp: Sump

