

# NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND  
OTHER HAZARDOUS MATERIALS



Canada



NT-NU 24-HOUR SPILL REPORT LINE


Tel: (867) 920-8130 • Fax: (867) 873-6924 • Email: spills@gov.nt.ca

REPORT LINE USE ONLY

<b>A</b>	Report Date: 03   07   23	Report Time: 11:00 am	<input checked="" type="checkbox"/> Original Spill Report <b>OR</b> <input type="checkbox"/> Update # _____ to the Original Spill Report		<b>Report Number:</b>
<b>B</b>	Occurrence Date: 03   06   23	Occurrence Time: 9:00 am			
<b>C</b>	Land Use Permit Number (if applicable):		Water Licence Number (if applicable): S18L3-003		
<b>D</b>	Geographic Place Name or Distance and Direction from the Named Location: Marten/Plarmigan Utilidor Easement, Norman Wells		Region: <input checked="" type="checkbox"/> NT <input type="checkbox"/> Nunavut <input type="checkbox"/> Adjacent Jurisdiction or Ocean		
<b>E</b>	Latitude: _____ Degrees _____ Minutes _____ Seconds		Longitude: _____ Degrees _____ Minutes _____ Seconds		
<b>F</b>	Responsible Party or Vessel Name: TOWN OF NORMAN WELLS		Responsible Party Address or Office Location: 3 Mackenzie drive		
<b>G</b>	Any Contractor Involved: Northridge Contracting Ltd		Contractor Address or Office Location:		
<b>H</b>	Product Spilled: <input type="checkbox"/> Potential Spill Waste water	Quantity in Litres, Kilograms or Cubic Metres: 200 liters	U.N. Number:		
<b>I</b>	Spill Source: sewer main clean out	Spill Cause: sewer blockage/ rags	Area of Contamination in Square Metres: 10 cubic meters		
<b>J</b>	Factors Affecting Spill or Recovery: snow/ ice	Describe Any Assistance Required: Vacuum truck and Steam unit	Hazards to Persons, Property or Environment: possible pathogenic organisms		
<b>K</b>	Additional Information, Comments, Actions Proposed or Taken to Contain, Recover or Dispose of Spilled Product and Contaminated Materials: Steam truck with mole to clear blockage in pipes Sewer truck sucked up gray water on the ground Added soda ash to affected area to spill to neutralize bacterial growth				
<b>L</b>	Reported to Spill Line by: Chris Buist	Position: Utilities Operator	Employer: Town of Norman Wells	Location Calling From: Norman Wells	Telephone: (867) 688-0619
<b>M</b>	Any Alternate Contact: Hugo Pabke	Position: Utilities Manager	Employer: Town of Norman Wells	Alternate Contact Location:	Alternate Telephone: (867) 587-3700

REPORT LINE USE ONLY

<b>N</b>	Received at Spill Line by:	Position:	Employer:	Location Called:	Report Line Number:
Lead Agency: <input type="checkbox"/> EC <input type="checkbox"/> CCG/TCMSS <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> AANDC <input type="checkbox"/> NEB <input type="checkbox"/> Other: _____			Significance: <input type="checkbox"/> Minor <input type="checkbox"/> Major <input type="checkbox"/> Unknown	File Status: <input type="checkbox"/> Open <input type="checkbox"/> Closed	
<b>Agency:</b>	<b>Contact Name:</b>	<b>Contact Time:</b>	<b>Remarks:</b>		
Lead Agency:					
First Support Agency:					
Second Support Agency:					
Third Support Agency:					



*norman wells*

## Supplemental Release Report

### General Information

NT-NU Spill Report #: 2023082  
Incident Date: March 6, 2023 Incident Time: 9:00 am  
Incident Location: Marten/Ptarmigan Utilidor Easement  
Licencee Name: Town of Norman Wells Licence No: S18L3-003  
Form Completed By: Hugo Pabke Phone Number: (867) 688-0669

### Volume Details

Product Released: Wastewater Volume Released: 200 Litres  
Contained: Yes ☒ No ☐

### Clean Up

Status: Complete ☒ Ongoing ☐  
If ongoing, anticipated clean up completion date: \_\_\_\_\_

Operational clean up details: Soda ash applied after spill area cleared. Debris removed from site.

### Incident Details

Description of circumstances leading to the release: Blockage in sewer main.

How was the release identified: Sewer inspection.

Steps taken to minimize, control or stop the release: Steamer used to thaw sewer blockage, vacuum truck used to hold back sewage during steaming.

Root cause and causal factors of the release: Blockage in sewer main.

Corrective actions, if any: Steamer used to clear sewer blockage.

Additional Comments: The town will complete added sewer cleaning and flushing during the summer to prevent this sort of spill from reoccurring.

Town of Norman Wells  
3 Mackenzie Drive, Box 5  
Norman Wells, NT  
X0E 0V0  
PH: (867) 587-3700

# NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND  
OTHER HAZARDOUS MATERIALS



Canada



NT-NU 24-HOUR SPILL REPORT LINE


Tel: (867) 920-8130 • Fax: (867) 873-6924 • Email: spills@gov.nt.ca

REPORT LINE USE ONLY

A	Report Date: 03   07   23	Report Time: 11:00 am	<input checked="" type="checkbox"/> Original Spill Report OR <input type="checkbox"/> Update # _____ to the Original Spill Report		Report Number:
B	Occurrence Date: 03   06   23	Occurrence Time: 10:10 am			
C	Land Use Permit Number (if applicable):		Water Licence Number (if applicable): S18L3-003		
D	Geographic Place Name or Distance and Direction from the Named Location: Falcon/ Sahcho Utilidor Easement, Norman Wells		Region: <input checked="" type="checkbox"/> NT <input type="checkbox"/> Nunavut <input type="checkbox"/> Adjacent Jurisdiction or Ocean		
E	Latitude: _____ Degrees _____ Minutes _____ Seconds		Longitude: _____ Degrees _____ Minutes _____ Seconds		
F	Responsible Party or Vessel Name: TOWN OF NORMAN WELLS		Responsible Party Address or Office Location: 3 Mackenzie drive		
G	Any Contractor Involved: Northridge Contracting Ltd		Contractor Address or Office Location:		
H	Product Spilled: <input type="checkbox"/> Potential Spill Waste water	Quantity in Litres, Kilograms or Cubic Metres: 1000 liters	U.N. Number:		
I	Spill Source: sewer main clean out	Spill Cause: sewer blockage/ rags / Ice	Area of Contamination in Square Metres: 30 Cubic meters		
J	Factors Affecting Spill or Recovery: snow/ ice	Describe Any Assistance Required: Vacuum truck and Steam unit	Hazards to Persons, Property or Environment: possible pathogenic organisms		
K	Additional Information, Comments, Actions Proposed or Taken to Contain, Recover or Dispose of Spilled Product and Contaminated Materials: Steam truck with mole to clear blockage in pipes Sewer truck sucked up spill on the ground Added soda ash to affected area to spill to neutralize bacterial growth				
L	Reported to Spill Line by: Chris Buist	Position: Utilities Operator	Employer: Town of Norman Wells	Location Calling From: Norman Wells	Telephone: (867) 688-0619
M	Any Alternate Contact: Hugo Pabke	Position: Utilities Manager	Employer: Town of Norman Wells	Alternate Contact Location:	Alternate Telephone: (867) 587-3700

REPORT LINE USE ONLY

N	Received at Spill Line by:	Position:	Employer:	Location Called:	Report Line Number:
Lead Agency: <input type="checkbox"/> EC <input type="checkbox"/> CCG/TCMSS <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> AANDC <input type="checkbox"/> NEB <input type="checkbox"/> Other: _____			Significance: <input type="checkbox"/> Minor <input type="checkbox"/> Major <input type="checkbox"/> Unknown	File Status: <input type="checkbox"/> Open <input type="checkbox"/> Closed	
Agency:	Contact Name:	Contact Time:	Remarks:		
Lead Agency:					
First Support Agency:					
Second Support Agency:					
Third Support Agency:					



## Supplemental Release Report

### General Information

NT-NU Spill Report #: 2023086

Incident Date: March 6, 2023

Incident Time: 10:10 am

Incident Location: Falcon/Sahcho Easement

Licencee Name: Town of Norman Wells

Licence No: S18L3-003

Form Completed By: Hugo Pabke

Phone Number: (867) 688-0669

### Volume Details

Product Released: Wastewater

Volume Released: 1000 Litres

Contained: Yes ☒ No ☐

### Clean Up

Status: Complete ☒ Ongoing ☐

If ongoing, anticipated clean up completion date: \_\_\_\_\_

Operational clean up details: Soda ash applied after spill area cleared. Debris removed from site.

### Incident Details

Description of circumstances leading to the release: Partial blockage in sewer main.

How was the release identified: Call from resident.

Steps taken to minimize, control or stop the release: Vacuum truck sucked partial blockage out of sewer main and sucked up liquid on ground.

Root cause and causal factors of the release: Partial blockage in sewer main.

Corrective actions, if any: Partial blockage in sewer main sucked out using a vacuum truck.

Additional Comments: The town will complete added sewer cleaning and flushing during the summer to prevent this sort of spill from reoccurring.

Town of Norman Wells  
3 Mackenzie Drive, Box 5  
Norman Wells, NT  
X0E 0V0  
PH: (867) 587-3700

# NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND  
OTHER HAZARDOUS MATERIALS



Canada



NT-NU 24-HOUR SPILL REPORT LINE

Tel: (867) 920-8130 • Fax: (867) 873-6924 • Email: spills@gov.nt.ca

REPORT LINE USE ONLY

A	Report Date:	05	07	23	Report Time:	1:00 pm	<input checked="" type="checkbox"/> Original Spill Report <b>OR</b> <input type="checkbox"/> Update # _____ to the Original Spill Report	Report Number:
	B	Occurrence Date:	05	06	23	Occurrence Time:		
C	Land Use Permit Number (if applicable):				Water Licence Number (if applicable): S18L3-003			
D	Geographic Place Name or Distance and Direction from the Named Location: Sewer Main Cleanout behind 9 Marten Avenue						Region: <input checked="" type="checkbox"/> NT <input type="checkbox"/> Nunavut <input type="checkbox"/> Adjacent Jurisdiction or Ocean	
E	Latitude: _____ Degrees _____ Minutes _____ Seconds				Longitude: _____ Degrees _____ Minutes _____ Seconds			
F	Responsible Party or Vessel Name: Town of Norman Wells				Responsible Party Address or Office Location: 3 Mackenzie drive			
G	Any Contractor Involved: Northridge Contracting Ltd				Contractor Address or Office Location:			
H	Product Spilled: <input type="checkbox"/> Potential Spill Waste water				Quantity in Litres, Kilograms or Cubic Metres: 1500 liters		U.N. Number:	
I	Spill Source: sewer main clean out				Spill Cause: sewer blockage		Area of Contamination in Square Metres: 8 cubic meters	
J	Factors Affecting Spill or Recovery: Spring thaw in progress				Describe Any Assistance Required: Vacuum truck		Hazards to Persons, Property or Environment: possible pathogenic organisms	
K	Additional Information, Comments, Actions Proposed or Taken to Contain, Recover or Dispose of Spilled Product and Contaminated Materials: Sewer Truck inserted hose into sewer main and sucked out obstruction Sewer truck sucked up gray water on the ground Soda ash will be spread on affected area to neutralize bacterial growth in the summer once there is less standing water in the area							
L	Reported to Spill Line by: Hugo Pabke		Position: Utilities Manager		Employer: Town of Norman Wells		Location Calling From: Norman Wells	
M	Any Alternate Contact:		Position:		Employer:		Alternate Contact Location: Telephone: (867) 688-0669	

REPORT LINE USE ONLY

N	Received at Spill Line by:	Position:	Employer:	Location Called:	Report Line Number:
Lead Agency: <input type="checkbox"/> EC <input type="checkbox"/> CCG/TCMSS <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> AANDC <input type="checkbox"/> NEB <input type="checkbox"/> Other: _____			Significance: <input type="checkbox"/> Minor <input type="checkbox"/> Major <input type="checkbox"/> Unknown		File Status: <input type="checkbox"/> Open <input type="checkbox"/> Closed
Agency:		Contact Name:	Contact Time:	Remarks:	
Lead Agency:					
First Support Agency:					
Second Support Agency:					
Third Support Agency:					

## Supplemental Release Report

### General Information

NT-NU Spill Report #: 2023185  
Incident Date: May 6, 2023 Incident Time: 1:30 pm  
Incident Location: Sewer main cleanout behind 9 Marten.  
Licencee Name: Town of Norman Wells Licence No: S18L3-003  
Form Completed By: Hugo Pabke Phone Number: (867) 688-0669

### Volume Details

Product Released: Wastewater Volume Released: 1500 Litres  
Contained: Yes ☒ No ☐

### Clean Up

Status: Complete ☒ Ongoing ☐  
If ongoing, anticipated clean up completion date: \_\_\_\_\_

Operational clean up details: Soda ash applied after area sucked clear of standing water. Debris removed from site. A clay berm was constructed around site. Soda ash re-applied after clay berm constructed.

### Incident Details

Description of circumstances leading to the release: Partial blockage in sewer main.

How was the release identified: Call from resident.

Steps taken to minimize, control or stop the release: Vacuum truck sucked partial blockage out of sewer main and sucked up liquid on ground.

Root cause and causal factors of the release: Partial blockage in sewer main.

Corrective actions, if any: Partial blockage in sewer main sucked out using a vacuum truck.

Additional Comments: The town will complete added sewer cleaning and flushing during the summer to prevent this sort of spill from reoccurring.



# NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND  
OTHER HAZARDOUS MATERIALS



Canada



## NT-NU 24-HOUR SPILL REPORT LINE

Tel: (867) 920-8130 • Fax: (867) 873-6924 • Email: [spills@gov.nt.ca](mailto:spills@gov.nt.ca)

### REPORT LINE USE ONLY

A	Report Date:	05	21	23	Report Time:	2:00 pm	<input checked="" type="checkbox"/> Original Spill Report <b>OR</b> <input type="checkbox"/> Update # _____ to the Original Spill Report	Report Number:
	B	Occurrence Date:	05	20	23	Occurrence Time:		
C	Land Use Permit Number (if applicable):				Water Licence Number (if applicable): S18L3-003			
D	Geographic Place Name or Distance and Direction from the Named Location: Lemming lane Utilidor Easement, Norman Wells						Region: <input checked="" type="checkbox"/> NT <input type="checkbox"/> Nunavut <input type="checkbox"/> Adjacent Jurisdiction or Ocean	
E	Latitude:				Longitude:			
	_____ Degrees _____ Minutes _____ Seconds				_____ Degrees _____ Minutes _____ Seconds			
F	Responsible Party or Vessel Name: TOWN OF NORMAN WELLS				Responsible Party Address or Office Location: 3 Mackenzie drive			
G	Any Contractor Involved: Northridge Contracting Ltd				Contractor Address or Office Location:			
H	Product Spilled: <input type="checkbox"/> Potential Spill Waste water				Quantity in Litres, Kilograms or Cubic Metres: 100 liters		U.N. Number:	
I	Spill Source: sewer main clean out				Spill Cause: sewer blockage		Area of Contamination in Square Metres: 10 cubic meters	
J	Factors Affecting Spill or Recovery:				Describe Any Assistance Required: Vacuum truck		Hazards to Persons, Property or Environment: possible pathogenic organisms	
K	Additional Information, Comments, Actions Proposed or Taken to Contain, Recover or Dispose of Spilled Product and Contaminated Materials: Sewer truck sucked up gray water on the ground and blockage Added soda ash to affected area to spill to neutralize bacterial growth							
L	Reported to Spill Line by: Chris Buist		Position: Water Operator		Employer: Town of Norman Wells		Location Calling From: Norman Wells	
							Telephone: (867) 688-0619	
M	Any Alternate Contact: Peter Tayag		Position: Wastewater operator		Employer: Town of Norman Wells		Alternate Contact Location: (867) 587-3700	

### REPORT LINE USE ONLY

N	Received at Spill Line by:	Position:	Employer:	Location Called:	Report Line Number:
	Lead Agency: <input type="checkbox"/> EC <input type="checkbox"/> CCG/TCMSS <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> AANDC <input type="checkbox"/> NEB <input type="checkbox"/> Other: _____	Significance: <input type="checkbox"/> Minor <input type="checkbox"/> Major <input type="checkbox"/> Unknown	File Status: <input type="checkbox"/> Open <input type="checkbox"/> Closed		
	Agency:	Contact Name:	Contact Time:	Remarks:	
	Lead Agency:				
	First Support Agency:				
	Second Support Agency:				
	Third Support Agency:				

## Supplemental Release Report

### General Information

NT-NU Spill Report #: 2023209  
Incident Date: May 20, 2023 Incident Time: 8:30 pm  
Incident Location: Lemming Lane Utilidor Easement  
Licencee Name: Town of Norman Wells Licence No: S18L3-003  
Form Completed By: Hugo Pabke Phone Number: (867) 688-0669

### Volume Details

Product Released: Wastewater Volume Released: 100 Litres  
Contained: Yes ☒ No ☐

### Clean Up

Status: Complete ☒ Ongoing ☐  
If ongoing, anticipated clean up completion date: \_\_\_\_\_

Operational clean up details: Soda ash applied after spill area cleared. Debris removed from site.

### Incident Details

Description of circumstances leading to the release: Partial blockage in sewer main.

How was the release identified: Call from resident.

Steps taken to minimize, control or stop the release: Vacuum truck sucked partial blockage out of sewer main and sucked up liquid on ground.

Root cause and causal factors of the release: Partial blockage in sewer main.

Corrective actions, if any: Partial blockage in sewer main sucked out using a vacuum truck.

Additional Comments: The town will complete added sewer cleaning and flushing during the summer to prevent this sort of spill from reoccurring.



# NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND  
OTHER HAZARDOUS MATERIALS



Canada



NT-NU 24-HOUR SPILL REPORT LINE


Tel: (867) 920-8130 • Fax: (867) 873-6924 • Email: spills@gov.nt.ca

REPORT LINE USE ONLY

A	Report Date:	12   01   23	Report Time:	3:30 pm	<input checked="" type="checkbox"/> Original Spill Report <b>OR</b> <input type="checkbox"/> Update # _____ to the Original Spill Report	Report Number:
	B	Occurrence Date:	12   01   23	Occurrence Time:		
C	Land Use Permit Number (if applicable):			Water Licence Number (if applicable): S18L3-003		
D	Geographic Place Name or Distance and Direction from the Named Location: Area Past Sewer Lift Station (Lot 419)				Region: <input checked="" type="checkbox"/> NT <input type="checkbox"/> Nunavut <input type="checkbox"/> Adjacent Jurisdiction or Ocean	
E	Latitude: _____ Degrees _____ Minutes _____ Seconds			Longitude: _____ Degrees _____ Minutes _____ Seconds		
F	Responsible Party or Vessel Name: TOWN OF NORMAN WELLS			Responsible Party Address or Office Location: 3 Mackenzie drive		
G	Any Contractor Involved: Northridge Contracting Ltd			Contractor Address or Office Location:		
H	Product Spilled: <input type="checkbox"/> Potential Spill Waste water		Quantity in Litres, Kilograms or Cubic Metres: 2000 Liters		U.N. Number:	
I	Spill Source: sewer main clean out		Spill Cause: sewer blockage/ rags		Area of Contamination in Square Metres: 20 square meters	
J	Factors Affecting Spill or Recovery:		Describe Any Assistance Required: Vacuum truck and Steam unit		Hazards to Persons, Property or Environment:	
K	Additional Information, Comments, Actions Proposed or Taken to Contain, Recover or Dispose of Spilled Product and Contaminated Materials: Steam truck with mole to clear blockage in pipes Sewer truck sucked up gray water on the ground and sucked obstruction out of sewer pipe Area has been fenced off to prevent public access					
L	Reported to Spill Line by: Hugo Pabke	Position: Utilities Manager	Employer: Town of Norman Wells	Location Calling From: Norman Wells	Telephone: (867) 688-0669	
M	Any Alternate Contact: Chris Buist	Position: Utilities Operator	Employer: Town of Norman Wells	Alternate Contact Location:	Alternate Telephone: (867) 587-3700	

REPORT LINE USE ONLY

N	Received at Spill Line by:	Position:	Employer:	Location Called:	Report Line Number:
Lead Agency: <input type="checkbox"/> EC <input type="checkbox"/> CCG/TCMSS <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> AANDC <input type="checkbox"/> NEB <input type="checkbox"/> Other: _____			Significance: <input type="checkbox"/> Minor <input type="checkbox"/> Major <input type="checkbox"/> Unknown		File Status: <input type="checkbox"/> Open <input type="checkbox"/> Closed
Agency:		Contact Name:	Contact Time:	Remarks:	
Lead Agency:					
First Support Agency:					
Second Support Agency:					
Third Support Agency:					



*norman wells*

## Supplemental Release Report

### General Information

NT-NU Spill Report #: 2023510

Incident Date: December 1, 2023

Incident Time: 11:00 am

Incident Location: Areas Past Sewer Lift Station (Lot 419)

Licencee Name: Town of Norman Wells

Licence No: S18L3-003

Form Completed By: Hugo Pabke

Phone Number: (867) 688-0669

### Volume Details

Product Released: Wastewater

Volume Released: 2000 Litres

Contained: Yes ☒ No ☐

### Clean Up

Status: Complete ☒ Ongoing ☐

If ongoing, anticipated clean up completion date: \_\_\_\_\_

Operational clean up details: Soda ash applied after spill area cleared.

### Incident Details

Description of circumstances leading to the release: Blockage in sewer main.

How was the release identified: Sewer inspection.

Steps taken to minimize, control or stop the release: Steamer used to thaw sewer blockage, vacuum truck used to hold back sewage during steaming.

Root cause and causal factors of the release: Blockage in sewer main.

Corrective actions, if any: Steamer used to clear sewer blockage.

Additional Comments: \_\_\_\_\_

Town of Norman Wells  
3 Mackenzie Drive, Box 5  
Norman Wells, NT  
X0E 0V0  
PH: (867) 587-3700