



Telephone: 867-587-7202
Fax: 867-587-2928

August 7, 2023

Enbridge Pipelines
110175 101 St. NW
Edmonton, AB T5J 2J9

Attention: Sarah McKenzie

File Number	S20P-003
Type of Operation	PIPELINES (existing)
Location	Camp

Dear Sarah McKenzie,

An inspection of the above noted operation was conducted by A/Manager, Resource Management Officer Meagan Betts and Wildfire Administrative Supervisor Bryson Rogers on June 16, 2023.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact the undersigned Inspector at 867-587-7202 or by email at meagan_betts@gov.nt.ca.

Sincerely,

Meagan Betts
A/Manager, Resource Management
Department of Environment and Climate Change, Land and Water Division
Sahtu Region

CC: Sahtu Land and Water Board
Trevor Bremner- Regional Superintendent, Department of Environment and Climate Change, Land and Water Division, Sahtu Region



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Enbridge Pipelines	Permit Expiry Date:	September 17, 2025
Land Use Permit No.	S20P-003	Previous Inspection:	March 21, 2023
Quarrying Permit No.	N/A	Inspection Date:	June 16, 2023
Contractor:	N/A	Subcontractor:	N/A
Location(s) Inspected:	Camp		
Current Stage of Operation:	Remediation		
Program Modifications Approved:	None		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Camp				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Historical / Archaeological Sites	A				
Ecological Resources	N/A				
Fuel Storage	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	N/I				
Matters not Inconsistent	N/A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	N/A				

Explanatory Remarks:

An aerial inspection for Land Use Permit S20P-003 was conducted via helicopter by two personnel from the Department of Environment and Climate Change on June 16, 2023. The inspection was limited to the camp near kilometer point (KP) 158 along the Mackenzie Valley Winter Road.

Camp:

The inspection occurred while maintenance and operational activities were inactive due to the season. The inspector confirmed that all equipment and material was demobilized from the site and that there continues to be no concerns regarding the cleanup efforts of this



ENVIRONMENTAL INSPECTION REPORT

project. As evident from Figure 1, there were no materials or debris left on site and the Inspector noted no evidence to suggest reason for concern with erosion or revegetation to date.

Future Inspections will occur to continue to monitor on-going project activities, however, the Inspector has no concerns to date regarding this work.

Representative Signature

Melvan Bells

Inspector's Signature

Date:	June 16, 2023	Permit #:	S20P-003	Page No:	2
-------	---------------	-----------	----------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Aerial image of camp area near KP 158 taken from approximately 630 ft while facing east

